

ToughShield

WARNING:

This application must
not be used when you
are in control of a
vehicle.

Accept

ToughShield



Blocked Drainage



Overgrown Vegetation



Fence Damage



Sign-Deformed



Debris/Litter



Sign - Poor Visibility



Lighting Issue



Surface Water




Infrastructure Damage



Surfacing Defect

Toughshield



SUBMIT



Toughshield

Retake

Issue: Overgrown Vegetation



SUBMIT





Defect Reports

Get Reports

Start Date *

27/05/2015

End Date *

02/06/2015

Area *

All

Defect Type *

All

Get Reports



Road	Time	Latitude	Longitude	Northing	Easting	Section	Image
M77	27/05/2015 15:00:00	55.7936478	-4.3413692	658075.90703	253305.86238	11455/05	Yes
A9	27/05/2015 19:48:34	58.6657391	-3.4829169	965141.33572	313834.12656	10515/50	Yes
A7	27/05/2015 19:48:47	55.2204874	-2.9709425	592236.48751	338328.63604	11006/40	Yes
A75	27/05/2015 19:48:56	55.0508548	-3.8030537	574415.06948	284908.41287	11528/60	Yes



Get Reports



Start Date *

27/05/2015

End Date *

02/06/2015

Area *

All

Defect Type *

Blocked Drainage

Get Reports



Road	Time	Latitude	Longitude	Northing	Easting	Section	Image
A95	27/05/2015 19:53:42	57.3555083	-3.5198349	830468.19391	308656.24271	10940/55	Yes
A9	27/05/2015 19:57:18	56.2408365	-3.8756437	706549.38621	283851.75968	10415/06	Yes
A9	27/05/2015 20:04:06	57.3074896	-3.9409678	825768.26113	283169.36522	10447/40	Yes
M74	30/05/2015 11:07:59	55.8245396	-4.0896821	661007.49939	269186.42937	10786/33	Yes
M6	02/06/2015 14:51:26	55.8622245	-4.2548914	665526.22139	258975.15694	14250/53	No

Export